



5 WAYS TO SAVE INDUSTRIAL FACILITIES

CHECK OUT THESE 5 WAYS TO SAVE AND APPLY THEM AT WORK AS YOUR FACILITIES ALLOW.

1. Ask your Unit Energy Manager (UEM) how to adjust or turn off the heat or AC when you are the last to leave your room or workspace.
2. Identify opportunities to shut down or unplug compressors or other large machinery, which pull electricity when not in use. Report opportunities to your UEM.
3. Close bay doors, if possible, when using heat or AC.
4. Turn off lights when you leave a room.
5. Don't let vehicles idle – this wastes a large amount of fuel over time. A typical truck burns approximately one gallon of diesel fuel for each hour it idles.

